



POOLE HARBOUR COMMISSIONERS
LOCAL NOTICE TO MARINERS
POOLE HARBOUR

No. 10/2017

9th April 2017

Rockley Channel East Cardinal Beacon

Mariners are advised that the East Cardinal Beacon in the entrance to the Rockley Channel is currently off station and an underwater obstruction may exist.

The Position of the possible obstruction is: 50° 42.820N
002° 01.104W

This position is marked by a yellow special mark with a light characteristic Fl(2)Y.5s

Mariners should navigate this area with extreme caution.

All vessels should monitor VHF channel 14.

Mariners are reminded that Radar, AIS, CCTV, telephone and VHF channels are recorded.

Captain B P Murphy
Harbour Master

ALL LOCAL NOTICES TO MARINERS ARE AVAILABLE ON THE PHC WEBSITE: www.phc.co.uk

HARBOUR OFFICE - 20 New Quay Road, Hamworthy, Poole, Dorset, BH15 4AF
Telephone: (01202) 440210 Fax: (01202) 440231 e-mail:harbourmaster@phc.co.uk